Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: AUSTIN 23-32H

Field Name: PARSHALL Well File #: 17122

Date Incident:1/12/2016Time Incident:09:00Facility ID Number:County:MOUNTRAILTwp: 154Rng: 90Sec: 32Qtr:

Location Description:

Submitted By: Danielle Dupay Received By:

Contact Person: Danielle Dupay

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 10 Barrels 10 Barrels 10 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/29/2016 Clean Up Concluded: 1/19/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

911 was called to respond but the treater fire was extinguished and the emergency responders were called off. The standing liquids were removed by a vac truck and a hydrovac will be used for cleanup of any contaminated soils along with repairs being made to the treater.

Wastes Disposal Location: Liquids were taken to SWD and solids TBD

Agencies Involved: New Town Fire Department

Updates

Date: 1/13/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of 10 barrels of oil, due to a fire, was contained within facility diking according to the report. NDIC retains oversight.